




PEGAS

350x400 A-CNC-LR-F



45° 0° 45°








mm	0°	45°*	45°*	 $\frac{b}{a \times b}$	 $\frac{a}{b}$
	350	320	320	X	X
	250*	180*	180*	X	X
 $\frac{a}{b}$ $a \times b$	400x350	330x120	330x120	400x210	400x180
 $\frac{b}{a}$ $a \times b$	400x350	260x350	210x350	400x210	400x180

*doporučené hodnoty / recommended values

**pouze v poloautomatickém režimu / only in semiautomatic mode

	 kW	 m/min	 mm	 kg
3x400V 50 Hz	3,0	20-100	4520x34x1,1	1325
L	Bmin	Bmax	Hmin	Hmax
2300	2350	2750	1570	2500
				V
				940



■ STANDARD ■ OPTION